


# Profile Mask User Manual

## 1. General introduction


The Profile Mask tool is used to crop out part of the profile, or to mask out parts of the profile, selected using a series of profile regions.

## 2. Parameters and outputs

|                   |                                                                           |                                                                                      |
|-------------------|---------------------------------------------------------------------------|--------------------------------------------------------------------------------------|
| Mode              | Choose whether to Crop the selected regions, or Mask the selected regions |  |
| Number of Regions | Assuming "Use Regions" is selected, specifies how many regions to use.    |                                                                                      |
| Region #          | According to the number of regions selected.                              |                                                                                      |

### 3. Example

Setting 3 regions as follows:



The output would depend on the mode of operation:

